Monday, 30/07/2007 9:10:41 AM Date: Use $\widehat{\ }$ Customer Job Number **Estimate Number** P.O. Number This Issue Proht Rev. First Issue **Previous Run** Written By Checked & Approved By Comment **Additional Product** Job Number: Seq. #: 1.0 Comment: PACKAGING RESOURCE #1 2.0

Linda Lacelle **Process Sheet**

: SMALL /MED FAB

Part Number : D35643 : REWORK **Drawing Number Project Number Drawing Revision** Material

Drawing Name

Due Date

: D35643

Qty: 21 Um: Each

PACKAGING 1

: 33764

: 10804 : NA

: 30/07/2007

: NIA

: 00015

Machine Or Operation: Description:

S.O. No. : NA

PACKAGING RESOURCE #1

WEARSHOE

21 x D3564-3 B33244

: CC-DAR01 Dart Aerospace Ltd.

D35643

WEARSHOE

remove from stk:



Comment: Qty.: 1.0000 Each(s)/Unit Total: 21.0000 Each(s)

3.0 SMALL FAB 1



SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

reform to remove aft joggle



4.0 QC5



INSPECT WORK TO CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP



PACKAGING RESOURCE #1



PACKAGING 1





Comment: PACKAGING RESOURCE #1

re-identify using new B/N

5.0

Da:e:

Monday, 30/07/2007 9:10:41 AM

User:

Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D35643

Job Number: 33764

Part Number: D35643

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



U 07.5/20

	renday: 30/07/2007 9 10:41 AM nda Lacelle	Process Sheet	Sp1.7 / Jugar	<u></u>
Latomer . 22 Number Esilmate Number L.), Number	: CC-DAR01 Dart Aerospace Ltd. : 33764 ~ / :r : 10804 : 🎤	Drawing Name Part Number	: D35643 : D35643	
is lasue Fisht Rev. First lasue Fishious Run	: 30/07/2007 S.O. No. : NA : NC : MA Type : SMALL /MED FAB : 00015	Drawing Number Project Number	REWORK LAN THE	4
iffen By Tracked & Appr Tracked & Tracked	:	Due Date	; 06/08/2007 Qty:	Um: Eac
ditional Produ	Jct.			
r; Namber:	CONTRACTOR			
Seg. #:	Machine Or Operation:	Description:		
1.0	PACKAGING 1	PACKAGING RESOURCE #1	ACADEMICA SERVICES SE	
Com 2.0	remove from stk: 21 x D3564-3 B33244	07-03-30	4	77 78-10 8-118-673-879-1-918-900-6-30-9 ₀₀₀₋₁₀₋₁₀ -0-0-10-10-1
	mest: Qty.: 1.0000 Each(s)/Unit Total: 21 WEARSHOE	.0000 Each(s)		
3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURC	E 1	
C-02 a	ment: SMALL & MEDIUM FAB RESOURCE 1 reform to remove aft joggle	107-30	9	
Antonia de la company de la co	ccs ment: INSPECT WORK TO CURRENT STEP	INSPECT WORK TO CURRENT ST	EP 57/07/20 ((4)
5.0 Cer :	PACKAGING 1 Ment: PACKAGING RESOURCE #1	PACKAGING RESOURCE #1		
. a. san proof-maken St. William (1871) (speeding - 1871)	re-identify using new B/N	/AUJ. 30	D (4)	

Monday, 30/07/2007 9:10:41 AM

Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D35643

Job Number: 33764

Part Number: D35643

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE

a - Completion

